Printed on: 5/27/2010 11:44:53 PM

National Transportation Safety Board			NTSB ID: CEN10RA135				Aircraft Registration Number: D-IEFA			
FACTUAL REPORT OC			Occurrence Date: 03/01/2010				Most Critical Injury: None			
AVIATION	Occurrence			Type: Incide	ent	Investigated B	ign			
Location/Time										
Nearest City/Place	State Zip		Zip C	Code	Local Time	Time Zone				
Stuttgart					0710	UTC				
Airport Proximity: Off Airport/Airstrip Distance From L				n Landing Facility:						
Aircraft Information Summary										
Aircraft Manufacturer				Model/Series				Type of Aircraft		
CESSNA				525/A			Airplane			
Revenue Sightseeing Flight: No	Air Medical Transport Flight: No									

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On March 1, 2010, at 0710 coordinated universal time, a Cessna 525A, German registered D-IEFA, owned by EFD - Eisele Flugdienst GmbH, was damaged when the left engine experienced an uncontained event near Stuttgart, Germany. Visual meteorological conditions prevailed at the time of the event. The pilot was not injured. The flight originated from Stuttgart, Germany, and was en route to Bremen, Germany.

The German investigators reported that the airplane was en route to Bremen for maintenance. During the climb, the left engine experienced an uncontained event. The flight returned to Stuttgart and landed without further incident.

The accident investigation is under the jurisdiction and control of the German government. This report is for informational purposes only and contains only information released by or obtained from the German government or the German Federal Bureau of Aircraft Accident Investigation. Further information pertaining to this accident may be obtained from:

German Federal Bureau of Aircraft Accident Investigation Bundesstelle für Flugunfalluntersuchung (BFU) Hermann-Blenk Strasse 16 38108 Braunschweig Germany Updated on Mar 11 2010 5:37PM

## National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: CEN10RA135

Occurrence Date: 03/01/2010

THEINIBALIONI				00/01/2010						
AVIATION		Occurr	ence Type							
Landing Facility/Approach In	formation	•								
Airport Name		А	irport ID:	Airport Elevation	Airport Elevation Runway Used			ay Lengt	h R	Runway Width
				Ft. MSI	_ N/A	4				
Runway Surface Type:		<u>'</u>		•	•		•			
Runway Surface Condition:										
Approach/Arrival Flown: NONE										
VFR Approach/Landing: None										
Aircraft Information										
Aircraft Manufacturer CESSNA			Model/ 525/A					Serial	Number	
			323/F	1						
Airworthiness Certificate(s):										
Landing Gear Type: Retractable	- Tricycle									
Amateur Built Acft? No	Number of Seats:		Certifie	d Max Gross Wt.	LBS Numbe			er of Engi	nes:	
			Engine Manufacturer: Model/Serie WILLIAMS FJ44 - 3A-						Rated Power:	
- Aircraft Inspection Information									<u> </u>	
Type of Last Inspection			Date of Las	t Inspection	Time Si	nce Last Inspe	Airframe Total Time			
Unknown							Н	Hours		
- Emergency Locator Transmitter (I	ELT) Information									
ELT Installed?/Type		ı	ELT Operated? ELT Aided in Locating A					ent Site?	?	
Owner/Operator Information										
Registered Aircraft Owner			Street A	address						
EFD Eisele Flugdienst GmbH			City	State	Zip Code					
Operator of Aircraft			Street A	ddress						
EFD Eisele Flugdienst GmbH					State	Zip Code				
Operator Does Business As:					0	perator Desigi	nator Co	ode:	<u> </u>	
- Type of U.S. Certificate(s) Held: N	None									
Air Carrier Operating Certificate(s):	:									
Operating Certificate:				Operator Certifi	cate:					
Regulation Flight Conducted Under	r: Non-U.S., Non-	Comme	rcial							
Type of Flight Operation Conducted	d: Positioning									
		FACTU	AL REPO	RT - AVIATION						Page 2

## National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: CEN10RA135

Occurrence Date: 03/01/2010

	工器人品	1 2							—							
	AVIATI	ON		Occurren	Occurrence Type: Incident											
First Pilo	t Information								•							
Name						City	State				te	Date of Birt	th	Age		
On File																
Sex: M	Seat Occupied	: Left	0	ccupational Pi	ilot? Yes					Cei	rtificat	e Numb	er:		•	
Certificate(s): Commercial																
Airplane R	ating(s): Mult	i-engine La	nd													
Rotorcraft/	Glider/LTA:															
Instrument	Rating(s):															
Instructor F	Rating(s):															
Current Bie	nnial Flight Revie	ew?														
Medical Ce	ert.: Unknown	Medica	al Cert. Stat	us:					I	Date of La	ast Me	edical E	xam:	m:		
- Flight Tin	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	N	light	Actual	Instrume	strument R			Glider		Lighter Than Air	
Total Time													1			
Pilot In Cor	mmand(PIC)															
Instructor																
Instruction	Received															
Last 90 Da	ys															
Last 30 Da	ys															
Last 24 Ho	urs															
Seatbelt Us	sed? Unknown	Shou	ulder Harnes	s Used? Unk	nown		Toxico	ology Pe	erform	ed? No		Se	cond Pilot?	, No		
Flight Pla	n/Itinerary															
Type of Flig	ght Plan Filed: U	nknown														
Departure I	Point						State Air			Airport Identifier			ture Time	<u> </u>	Time Zone	
Stuttgard																
Destination	1						State Airport Ide				entifier					
Bremen																
Type of Cle	earance: Unkno	wn														
Type of Air	space: Unkno	own														
Weather	Information															
Source of	Wx Information:															
	Unkno	own														
				FACTUAI	DEDODT	A 3.71	ATION	NT.							Page 3	
				FACIUAL		- A V I	AIR	N							i aye o	

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: CEN10RA135

Occurrence Date: 03/01/2010

	AVIATION	Occurren	Occurrence Type: Incident										
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF Elevat	stance Fro	m Acci	dent Site	rom Accident Si	te					
EDDS	0720	UTC	Ft	. MSL				NM			Deg	ı. Mag.	
Sky/Lowes	st Cloud Condition: Few			2	2000 Ft. A	GL	Condition of Light: Day						
Lowest Ce	iling:	Ft.	AGL	Visibi	lity:	6.2	SM	Alti	meter:	"Hg			
Temperatu	ıre: 5 °C [	Dew Point:	-1 °C	Weath	ner Condit	tions at Ac	cident S	Site: Visual (	Cond	litions			
Wind Direc	ction: 120	Wind Speed	d: 3		Wind	l Gusts:							
Visibility (R	RVR): Ft.	Visibility (R	VV)	SM									
Precip and	l/or Obscuration:												
Accident	Information												
Aircraft Dar	mage: Substantial		Aircraft Fir	Aircraft Fire: None					Aircraft Explosion None				
			•										
- Injury Su	mmary Matrix	Fatal Se	erious Min	or	None	TOTAL							
First Pi	lot				1	,	1						
Second	d Pilot												
Studen	t Pilot						7						
Flight I	nstructor						7						
Check	Pilot						7						
Flight E	Engineer						7						
Cabin A	Attendants						7						
Other C	Crew						7						
Passen	ngers						7						
- TOTAL A	ABOARD -				1	,	1						
Other G	Ground						7						
- GRAND	O TOTAL -				1	,	1						

National Transportation Safety Board

## FACTUAL REPORT AVIATION

NTSB ID: CEN10RA135

Occurrence Date: 03/01/2010

Occurrence Type: Incident

Δ	dm	inis	trativ	r⊵ Int	f∩rm	ation
$\overline{}$	ulli	บบอ	uauv			alioi

Investigator-In-Charge (IIC)

Jennifer Rodi

Additional Persons Participating in This Accident/Incident Investigation:

Thomas Karge German BFU - IIC

Steve Miller Cessna Aircraft Company Wichita, KS

Frank Smith Williams International Walled Lake, MI